

VERHUURGEGEVENS - 2e Verdieping






























Opdrachtgever: **STONE22**

Rapportnummer : 20135470_1018GW_001
 Certificaatnummer : 20135470_1018GW_001A

Gebouw : 1018GW
 Adres : Sarphatistraat 370
 Plaats : Amsterdam
 Datum : 02-06-2014

Bouwlaag : 2e Verdieping
 Certificaat **A**

Huurders:

	1018GW - C 1		1018GW - C 25
	1018GW - C 10		1018GW - C 26
	1018GW - C 11		1018GW - C 27
	1018GW - C 12		1018GW - C 3
	1018GW - C 14		1018GW - C 4
	1018GW - C 15		1018GW - C 5
	1018GW - C 16		1018GW - C 6
	1018GW - C 17		1018GW - C 7
	1018GW - C 18		1018GW - C 8
	1018GW - C 19		1018GW - C 9
	1018GW - C 2		1018GW - VR 02.01
	1018GW - C 20		1018GW - VR 02.02
	1018GW - C 21		Toeslag bouwlaagniveau
	1018GW - C 22		
	1018GW - C 23		
	1018GW - C 24		

Contour:



Opmerkingen:

- Meetvoering en ruimtegebruik van ruimte(n) niet toegankelijk voor inspectie (NTI) zijn niet gecontroleerd op locatie.

